



Special Note For BestTrack

We are supplying a mounting bar for BestTrack tracks.

1. Remove the mounting bar from the timer by removing the screws in the feet of the timer. Attach the mounting bar to the track by sliding the head of the hex head bolts into the channel on the bottom of the track.
2. Position these bolts next to the largest hole in the track.
3. Set the bar with the sensors and foam into the largest hole.
4. The sensors we supply for use with the BestTrack track have black 3/8" adapters installed.
5. Make sure the sensors are not caught so that they are facing sideways. They must face straight up.
6. Fasten down the bar to the track by tightening the nuts on the bolts that were slid into the channel.
7. Reconnect the timer to the bar either before installing the displays or after.



However, be **careful** with the display panel. It is **fragile** and should not be used to prop up the track. Follow the quick start instructions to continue to install the panel and connect the timer. The quick start instructions also contain information about connecting the timer to a computer.

Make sure that you insert the sensors in the correct direction. The plug should be on the right side when you are looking at the front of the timer. The front of the timer should be facing the starting gate.